

# Vehicle History Report

#### Audi A5

Located in : **Poland** Vehicle reference:

**WAULFAFR4EAXXXXXX** 

Model Year : **2014** Body Type : **Coupe** Fuel Type : **Petrol** 

Engine Size: 1984 cm3

Engine Power: 162kW/220 hp

**Get American Report** 

Salvage Title Issued

**Accident Reported** 

**Imported Vehicle** 

Number of Odometer readings: 8

## **Quick Check**

Stolen

Not Reported Stolen

**Identity Check** 

Not Reported Scrapped

**Damage** 

**Accident Reported** 

No issue reported

 $\checkmark$ 

No issue reported



**Accident** 

A **CheckCarz Vehicle History Report** is based on Information Supplied to CheckCarz. Other Information about this vehicle, including problems, may not have been reported to CheckCarz. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better descision about yout next car.

## **Highlights**





Number of owners: 2

Number of Transfers: 1



**Odometer** 



128315

Last Reported: 2021- 09-07

Vehicle Age



Vehicle Year 2014

First Registration Date: 2014-07-01





Latest Inspection: 2021-09-07



# **History Information**

Date	Mileage	Event
2014-07-01		First Registration Abroad
2014-08-21	65 mile 105 km	Odometer Reading Reported
2015-10-04		Accident Reported in United Stated



#### **Accident**

This vehicle has had an Accident. Have it inspected by a mechanic before purchasing.

2015-11-25 18,511 mile Insurance Claim reported in United States 29,790 km Salvage Title was issued in United States



# Salvage Title

This vehicle had a salvage title issued in USA. Check the condition of the vehicle with a mechanic before purchasing.

2015-12-27  Imported from United States to Lithuania  Damage reported in Lithuania Damage Areas:  • Vehicle Damage on all sides  Damage Reported for:  • Air-conditioning  • Windshield / Glass  • Upholstery  • Passive safety System  • Chassis  • External Lighting  • Suspension System  • Active Safety System  • Body Parts  2019-08-29  94,000 km  Damage reported in Germany Damage area:  • Right Front  • Front Damage reported for:  • Body Parts  2020-06-17  Accident reported in Germany Damage Areas:  • Right Front  • Front  • Front  • Left front Damage Areas:  • Air-conditioning • Chassis  • External Lighting • Active Safety System  • Body Parts				
Damage Areas:  • Vehicle Damage on all sides  Damage Reported for:  • Air-conditioning  • Windshield / Glass  • Upholstery  • Passive safety System  • Chassis  • External Lighting  • Suspension System  • Active Safety System  • Body Parts  2019-08-29  94,000 km  Damage reported in Germany Damage area:  • Right Front  • Front  Damage reported for:  • Body Parts  2020-06-17  Accident reported in Germany Damage Areas:  • Right Front  • Front  Damage Reported for:  • Body Parts		2015-12-27		Imported from United States to Lithuania
Damage area:  Right Front Front Damage reported for: Body Parts  Accident reported in Germany Damage Areas: Right Front Front Front Left front Damage Reported for: Air-conditioning Chassis External Lighting Active Safety System		2016-02-15		Damage Areas:  • Vehicle Damage on all sides  Damage Reported for:  • Air-conditioning  • Windshield / Glass  • Upholstery  • Passive safety System  • Chassis  • External Lighting  • Suspension System  • Active Safety System
Damage Areas:  • Right Front  • Front  • Left front  Damage Reported for:  • Air-conditioning  • Chassis  • External Lighting  • Active Safety System		2019-08-29	94,000 km	Damage area:  • Right Front  • Front  Damage reported for:
		2020-06-17		Damage Areas:  Right Front Front  Left front  Damage Reported for:  Air-conditioning Chassis External Lighting Active Safety System

# **History Information**

Date Mileage Event



# **Accident**

This vehicle has had an Accident. Have it inspected by a mechanic before purchasing.

2020-06-22	116,500 km	Odometer Reading Reported
2020-09-09	116,720 km	Inspected in Poland Inspection Type: Regular Inspection Passed
2020-09-15		Imported from Germany to Poland Registered in Poland New Owner Reported Owner Type: Private Individual
2021-08-16	128,000 km	Damage reported in Poland Damage Area: • Left Rear • Rear
2021-08-18	127,830 km	Odometer Reading Reported
2021-09-07	128,315 km	Inspected in Poland Inspection Type: Regular Inspection Passed
2021-09-16		Damage reported in Poland  Damage Area:  • Left Rear  • Rear
2021-09-19		Vehicle Insured Liability insurance valid until 2022-09-18
2022-02-14		Damage reported in Poland
2022-05-11		New Owner Reported Owner Type: Private Individual

Based on data reviewed from 22 countries in Europe and North America



## **CheckCarz Glossary**

# **Model Year**

This term is Defined by the manufacturer but it is typically the year the vehickle is built. If the model year does not appear on the CheckCraz report, it is because the manufacturer did not include this information in the VIN. Model year can normally be determined by the vehicle age.

# **Quick Check**

A snapshot of the information Checkcarz has abstructed from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publically imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CheckCarz from various sources. Additional information aout this vehicle, including these potential prolems, may exist and may not have been reported to CheckCarz.

# Vehicle Reference

User-provided value to identify the vehicle during CheckCarz Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

